

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER No. CA-125-H

HAER
CAL
1-OAK
124-

Oakland Army Base, Vehicle Maintenance Shop
(Building No. 99)
Attu Street at Corregidor Avenue
Oakland
Alameda County
California

Adrian Ordenana, Photographer (all photographs taken in 1994)

Note: Photographs of building drawings were reproduced from originals on file at the Installation Engineering Office, Oakland Army Base, Oakland, California. All photographs are 8" x 10" enlargements from 4" x 5" negatives.

- CA-125-H-1 NORTH FACE.
- CA-125-H-2 OBLIQUE VIEW OF EAST AND NORTH FACES.
- CA-125-H-3 OBLIQUE VIEW OF WEST AND SOUTH FACES.
- CA-125-H-4 INTERIOR VIEW TOWARD NORTH END OF BUILDING, TAKEN
FROM CENTER.
- CA-125-H-5 CROSS SECTION OF BUILDING TRUSS & PLAN,
SHEET NO. 101-2.
- CA-125-H-6 SITE PLAN & ELEVATIONS, SHEET NO. 101-2.
- CA-125-H-7 Photographic copy (reduced to 4 x 5 from 8 X 10 black and white
paper reproduction in 1941 appraisal by E.E. Malloy at the
Engineering Office, Oakland Army Base, California). Photograph
taken between June 1940 and January 1941 by unknown photogra-
pher. PARTIAL SOUTH ELEVATION OF VEHICLE MAINTENANCE SHOP (BLDG. 99).